

OXC-0823

Copy \_\_\_ of \_\_\_

19 August 1960

25X1A

MEMORANDUM FOR : The Record

SUBJECT : OXCART Support in Development Projects Division

The following personnel have been designated by Branches or Sections as primary contacts in OXCART support matters:

|                               |   |
|-------------------------------|---|
| Security                      | : |
| Cover                         | : |
| Personnel                     | : |
| Operations                    | : |
| Construction                  | : |
| Development Branch            | : |
| Cameras                       | : |
| Engines                       | : |
| Air Frame and Related Systems | : |
| Elint and Communications      | : |
| Communications                | : |



Administration, Contracts, Finance, Materiel, and Technical Analysis  
Chiefs furnish support on an on-call basis.

JOHN PARANGOSKY  
Deputy Chief, Development Branch  
DPD-DD/P

DC/DB/DPD/JPARANGOSKY:mjw  
Distribution: 0 & 1 - DC/DB/DPD  
1 - A/CH/DPD  
1 - RI/DPD

Approved For Release 2001/07/27 : CIA-RDP81B00879R001000030006-6

19 August 1960

DOCUMENT NO. \_\_\_\_\_  
NO CHANGE IN CLASS. ☒   
☐ DECLASSIFIED  
CLASS. CHANGED TO: TS S C  
NEXT REVIEW DATE: 2012  
AUTH: HR 70-2  
DATE: 5/2/82 REVIEWER: 064540

SECRET

CXC-0322  
Copy 7 of 7

19 August 1960

MEMORANDUM FOR THE RECORD

SUBJECT : Storage and Handling - FMA 523 Fuel  
For J44D-204 Engine

25X1A

REFERENCE: [REDACTED] 090 (IN 30870)

1. As outlined in reference message, engine contractor testing reveals that thermal stability of subject fuel is adversely affected by contact with copper and/or silver. The magnitude of this effect is a function of and increases with copper/silver concentration, residence time, and temperature. Thermal stability therefore can be destroyed over long periods of time with very slight concentrations of copper or silver.

2. Special precautions will be required in the area of storage and handling storage facilities and in the periodic cleaning of these facilities so that the use of cleaning equipment such as copper wire brushes is prohibited.

SIGNED

[REDACTED]  
Development Branch  
DPD-45/P

25X1A

Distribution:

1-DPD/DB  
2-OD/P  
3-C/DB/DPD  
4-5-DPD/Material  
6-DPD/DB  
7-DPD/RI

25X1A

DPD/DB/[REDACTED] (19 August 1960)

DOCUMENT NO. \_\_\_\_\_  
NO CHANGE IN CLASS. ☒   
☐ DECLASSIFIED  
CLASS. ENHANCED TO: TS S G  
NEXT REVIEW DATE: 2012  
AUTH: NE 1-2  
DATE: 5/2/82 REVIEWER: 064540

SECRET